



Release Lanyard Project

April 26th 2013

By: Andrew Baker, Tim Haynes, Styson Koide, David Lofgreen, Carly Siewerth, & Chris Temme

Overview

- Problem Statement
- Current Design
- New Design
- Testing
- Gantt Chart
- Conclusion
- References


Problem Statement


- Issues with freezing temperatures and debris
- Issues not activating weapons system
- Issues with poor installation
- Keep new design under \$300

General Constraints


- ▶ Temperature Range –60°F to 200°F
- Activation Force of 35–60lb.
- Breaking force of linkage 75lb.

Current CAD Design







Current Activation Slider




New Slider Design




New CAD Design






Northern Arizona University Department of Mechanical Engineering

New Activation Slider




New Activation Slider




Comparing

	Current Design	New Design	Reduction (%)	
Volume (in³)	5.50	5.36	-2.55	
Mass	0.21	0.21	-0.28	
S.A. (in²)	63.22	58.84	-6.93	
Concerning S.A. (in ²)	11.48	6.74	-41.29	
Mechanical Components	64.00	52.00	-18.75	
Assembly Operations	6.00	4.00	-33.33	
Machining Hours	2.60	2.10	-19.23	
Machining Costs (\$)	200.00	150.00	-25.0	


FEA Model Testing






Model Testing


- Materials
 - Battery
 - Light
 - Electrical wire
 - Battery mount






Experimental Testing


- 30 minute freeze time
- Spray every 10 minutes
- 2 types of freezing orientations



Vertical (Moderate Icing)





Horizontal (Heavy Icing)




Northern Arizona University Department of Mechanical Engineering

Testing Conditions (Moderate)









Problem Regions

Northern Arizona University
Department of Mechanical Engineering

Testing Conditions (Heavy)






Problem Regions

Testing Results

	No Ice Build-up	Moderate		Heavy			
Weight (lbs.)	1	1	2	3	1	2	3
35	Pass	Fail	Pass	Fail	Fail	Fail	Fail
40	Pass	Pass	Fail	Fail	Fail	Fail	Fail
45	Pass	Pass	Fail	Fail	Fail	Fail	Fail
50	Pass	Pass	Fail	Pass	Pass	Pass	Fail
55	Pass	Pass	Pass	Pass	Pass	*Fail*	Fail
60	Pass	Pass	Pass	Pass	Pass	Pass	Pass

Fail



Switch Failure

Conclusion

- Problem Statement
 - Issues with freezing temperature and debris
 - Not activation
 - Poor installation
- Current Design
 - Failing under extreme conditions
- New Designs
 - Include new slider arm, battery mount, and switch placement
- Gantt Chart

References

- Stephen Larimore
 - Raytheon Department Manager
- Kelly Convington
 - Raytheon Mechanical Engineer
- http://chemistry.about.com/od/nitrogen/f/What-Is-The-Temperature-Of-Liquid-Nitrogen.htm

Questions?

Tim Haynes