






DIMENSION SURFACE F	ES: +/- 0.02mm	NETERS	FINISH:				DEBURR BREAK SI EDGES
	NAME	SIG	NATURE	DATE			
DRAWN							
CHK'D							
APPV'D							
MFG							
Q.A					MATERIAL	AL:	
					Ceramic		
					WEIGHT:		
4				4	3		




















2 1	
	F
	E
	D
	С
R AND SHARP DO NOT SCALE DRAWING REVISION	В
Copper Clamp	
DWG NO. A3 SCALE:4:1 SHEET 1 OF 1 2 1	A





	2		1		
					F
					E
					D
					С
RR AND S SHARP S	DO NOT SCALE DE	RAWING	REVISION		В
	Uppe DWG NO. TPDSIM SCALE:4:1 2			- A3	A



DWG NO.
SCALE:1:1
2

TITLE:

DSIMS Design

A3

A

Sample Holder Assembly

	QTY.	D. PART NUMBER QTY.		EM NO.
	1		le	1
	3		earing	2
	1	Insulator Base		
	2	Eyebolt		
C	2	Hex Bolt 16mm		
	2	Set Screw		
	2	Hex Nut		
	2	Hex Bolt 18mm		
	2	Washer		
	2	Copper Clamp		
	1	Sample		
B	2	Upper Copper Clamp		
	N	REVISIO	D NOT SCALE DRAWING	IRR AND K SHARP
				ES

F

Е

D

